



802.1ad HW acceleration and MTU handling

Toshiaki Makita NTT Open Source Software Center

Proceedings of netdev 0.1, Feb 14-17, 2015, Ottawa, On, Canada


Copyright © 2015 NTT Corp. All Rights Reserved.




- Discussion on 802.1ad issues and implementation to address them
- Offloading: TSO
 - dev->vlan_features cannot handle multiple vlans
- Offloading: Vlan insert/strip
 - There is no space for HW accelerating inner vlan
- MTU (Tx/Rx buffer size)
 - Received double tagged large vlan packets are dropped by default (oversize error)



outer tag double tagged packet 🗸 eth0 SW 3 Copyright © 2015 NTT Corp. All Rights Reserved.






802.1ad and Linux

outer tag








Copyright © 2015 NTT Corp. All Rights Reserved.

NIC capability check for vlan





Need stacked vlan features for each physical device

• Some NICs seem topolege able 1, to 4-th and len, double tagged TSO



Approach



- Make dev->vlan_features array? (vlan_features[2])
 - The number of tags are limited to array's size

•Use ndo_features_check()?


- More flexible
- Need dflt_features_check() to drop double tagged TSO by default?
- Other thoughts?





insert/strip tag for stacked vlan

 Bridge internally insert/strip second tags when using vlan_filtering



Approach



•Use skb->cb[]?

- Bridge-specific solution
- Cannot be used for vlan offload on NIC

•Make skb->vlan_tci array (vlan_tci[2])?


- The number of tags are limited to array's size
- •Any other way?







 MTU-sized double tagged packet is dropped by default





Copyright © 2015 NTT Corp. All Rights Reserved. 9



• Looks like a strange random failure

- Ping is OK
- TCP connection can be established
- SSH is mostly OK
- Only large packet is discarded
- Hard to identify the root cause for users

Workaround varies driver by driver

- Setting MTU to 1504 would work in most cases
- Sometimes 1508/9000 is needed depending on drivers
- Bad experience for users...



Approach



• Always reserve 4bytes more room?

- Maybe overkill for a kind of corner case
- Some driver changes behavior if buffer size is more than 1522
 - e.g. e1000e uses packet split descriptor

Automatically adjust buffer size on creating 802.1ad device

- introduce ndo_enc_header_size()
- bridge/vlan_dev calls lower_dev->ndo_enc_header_size()
- Can be used for appropriate tx buffer size
- Other protocols (e.g. mpls) could also use it
- Any other way?

